

Division of Oil, Gas, & Mining
Mining Report

01/22/93

MINE ID: S047036

MINE NAME: CAMERON #1 PROJECT

OPERATOR: NATIVE ASPHALT COMPANY
CONTACT: MARK F LINDSEY
ADDRESS: 136 EAST SOUTH TEMPLE
UNIVERSITY CLUB BLDG. ST.
SALT LAKE CITY UT 84111
PHONE: (801)532-7510

Surface Owner: PRIVATE
Mineral Owner: PRIVATE

BLM #:
Lease #:

Qtr-Qtr-Qtr1	Qtr-Qtr1	Qtr1	Qtr-Qtr-Qtr2	Qtr-Qtr2	Qtr2	Sec	Range	Town
	NE	SW				31	22.0E	5.0S

Permit Status: APP

Mine Type [(S)urface, (U)nderground]: S

Mine Status (PRO,ACT,SUS,RET): ACT

Acreage: 5

Minerals Mined
STONE

DATE
RECEIVED

TENTATIVE APPROVAL
DATE

FINAL APPROVAL
DATE

LAST INSPECTED

12/07/88

/ /

12/07/88

05/20/92

BOND TYPE: N/A

BOND AMOUNT:

ANNUAL REPORT YEAR: 92

	YTD	Total			
NONCOMP NOTICES:	1	1	DATE ISSUED:	09/05/90	DATE RESOLVED: / /
VIOLATIONS:	0	0	DATE ISSUED:	/ /	DATE RESOLVED: / /
REVISIONS:	0	0	DATE REC'D:	/ /	DATE APPROVED: / /
AMENDMENTS:	0	0	DATE REC'D:	/ /	DATE APPROVED: / /

COMMENTS:

OPERATOR DID SOME RECLAMATION WORK IN HOPES TO MAINTAIN SMALL MINE STATUS. WORK IS NOT DESIRABLE. SEE FIELD INSPECTION MEMO FOR DETAILS ON THIS WORK. OPERATOR HAS SUBMITTED ANOTHER SMO FOR SAME VACINITY BRINGING THE TOTAL ACREAGE TO @7.5 ACRES. THIS NEEDS TO BE CHANGED TO A LARGE MINE OPERATION & BECOME BONDED. INSPECTION MADE TO COORDINATE STAKING OF DISTURBED AREA PRIOR TO LAND SURVEY. TOPSOIL STORAGE AREAS NEED IDENTIFIED & POSSIBLY STABILIZED W/SEED MIX.